


Virtex-II Pro SEE Test Methods and Results

David Petrick¹, Wesley Powell¹,
James Howard²

¹NASA Goddard Space Flight Center, Greenbelt, MD 20771

²Jackson & Tull, Seabrook, MD 20706



Abstract

The Xilinx Virtex-II Pro is a platform FPGA that embeds multiple microprocessors within the fabric of an SRAM-based reprogrammable FPGA. The variety and quantity of resources provided by this family of devices make them very attractive for spaceflight applications. However, these devices will be susceptible to single event effects (SEE), which must be mitigated.


To use the Virtex-II Pro reliably in space applications, these devices must first be tested to determine if they are susceptible to single event latchup (SEL), the degree to which they are susceptible to single event upsets (SEU) and single event transients (SET), and how these effects are manifested in the device. With this information, mitigations schemes can be developed and tested that address the specific susceptibilities of these devices.

This initial SEE test uses a commercial off the shelf Virtex-II Pro evaluation board, with a single processor XC2VP7 FPGA. The FPGA on this board is an acid etched device, which can be partially covered with a shield. The shield covers a portion of the logic, routing, and memory resources along with some of the RocketIO transceivers. The processor, along with a large portion of logic, routing, memory, and transceivers are left exposed.

This test will be performed at the Cyclotron Laboratories at Texas A&M University and Michigan State University using ions of varying energy levels and fluencies.




Virtex-II Pro FPGA




XC2VP7-FG456


- 0.13 μ m CMOS Process
- V_{CCINT} : 1.5V
- 4.4 Mb Configuration Memory
- 1 PowerPC 405 Processor
- 8 RocketIO Tranceivers
- 44 18x18 Multipliers
- 44 18Kb Block RAM
- 4 DCMs




Virtex-II Pro acid etched to expose die and MGTs



Memec Test Board




Petrack_P226




Radiation Test Details

- Testing performed at the Cyclotron labs at Texas A&M and Michigan State Universities
- Tested 3 identical boards, each populated with a delidded Virtex-II Pro FPGA
- Beam info
 - Ions: Ar, Kr, Ne, Xe, Cu
 - Flux: $2.5E2 - 3.2E5$
 - LET: $2.8 - 53.9 \text{ MeV-cm}^2/\text{mg}$
- Initial testing focus: SEL, SEFI, SEU




Test Procedure

- Shield selected logic with custom brass mask
- Program FPGA via PROM or JTAG
- Record strip chart power data through GPIB
- Record logic mismatch error counter data through RS-422
- Record custom PowerPC/MGT data through RS-232
- Upon device upset, document how communication is reestablished with the FPGA in following order:
 1. Software Reset
 2. Hardware Reset
 3. Reprogram FPGA
 4. Cycle FPGA Power
- Record number of configuration bit upsets via iMPACT
- Conduct multiple runs using all boards and variety of LET
- Record data with and without PowerPC instantiated in design




Test Setup Diagram





FPGA Test Design




- Xilinx BERT Application
 - 2 MGTs in loopback (tx -> rx)
 - PRS data drives MGT tx pins
 - PowerPC reports MGT status to PC via RS-232 port

```
Q50335088_test64
3775: >>>ITERATION 187
3776: --- MGT6 Status ---
3777: Received Frames: 9,068 M + 517,592
3778: Dropped Frames: 4
3779: Total Bit Errors: 4
3780: Error Factor: 165,318,706
3781: Line Rate : 2,505 Mbps
3782: Bit Error Rate : 21x10^-12
3783: Data Pattern : 3-PRBS7: 1+x^6+x^7
3784: Link-1 Abort-0 PowrDwn-0 TxInhibit-0 Loopbk-00
3785: --- MGT7 Status ---
3786: Received Frames: 9,068 M + 519,032
3787: Dropped Frames: 0
3788: Total Bit Errors: 0
3789: Error Factor: infinite
3790: Line Rate : 2,505 Mbps
3791: Bit Error Rate : 0
3792: Data Pattern : 3-PRBS7: 1+x^6+x^7
3793: Link-1 Abort-0 PowrDwn-0 TxInhibit-0 Loopbk-00
```


Petrick_P226

- SEU Detection Logic
 - ‘Logic Block’ units are identical
 - ‘Logic Block’ contents: 18x18 Mult, 1024x18 BRAM, 512x1 DFF Shift Reg, 256x4 SRL Shift Reg
 - ‘Logic Block B’ exposed to radiation
 - PC counts logic mismatches







Device Shielding Techniques




Virtex-II Pro Design Floorplan




Brass Mask Placement




Exposure of
PowerPC,
Logic Block B,
& 1 MGT



Isolation of
1 MGT





SEFI Data







SEE Data – MGT Bit Errors






SEE Data – Configuration Upsets








Constant Current Ramping




- Observations initially made when die was fully exposed during latch-up testing
- Ramp rate a function of radiation characteristics, logic usage, and die exposure
- Device either reconfigures or causes power-on reset (?)
 - Current ramps from nominal I_{CC} and $\sim 3.3A$, I_{CC} then drops to 0A, device reloads configuration bringing I_{CC} back up to nominal where it continues to ramp
- Not a function of Over Current Protection setting (unless $OCP < 3.3A$, then current cycles at this limit)
- Does not occur when FPGA irradiated without initially loading configuration file




Constant Current Plots






Conclusions

- No destructive SEL event observed to a LET of 53.9 MeV-cm²/mg and a fluency of 10⁷ Ions/cm²
- (Preliminary) The configuration memory and PowerPC have high susceptibility to radiation
 - 400,000+ configuration errors recorded during two short runs
 - SEFIs occurred too quickly to collect enough data on the PowerPC
- Action required to reestablish device functionality
 - Reprogram: 70%, Software Reset: 28%, Power Cycle: 2%
- Other observations
 - Jumps in the PowerPC instruction set
 - Lost JTAG capability twice during SEL testing
 - Cyclical current ramping
 - PowerPC reset itself twice during tests




Lessons Learned

- Hard to extract valid data from 'SEU Detection Logic' due to the quick accumulation of configuration bit upsets
 - Consider board with SelectMAP port to allow scrubbing
- Acid etching delidding process is very difficult with this package
 - Consider flip-chip package in conjunction with a socketed board
- Must use microscope when performing mask alignment
 - Misplaced mask caused unexpected SEEs



Future Work

- Continue radiation testing to gather detailed data to support conclusions on each device failure event
 - Various iterations with different logic architectures which focus on different elements of the Virtex-II Pro
 - Tailor tests to allow changes in clock frequency and temp
- Research SEU mitigation techniques
 - Xilinx TMR tool
 - Partial reconfiguration (scrubbing)
 - Use of redundant MGTs and PowerPCs with voting circuitry



Acronym List

- BERT: Bit Error Rate Test
- DCM: Digital Clock Manager
- LET: Linear Energy Transfer
- MGT: Multi-Gigabit Transceiver
- SEE: Single Event Effect
- SEFI: Single Event Functional Interrupt
- SEL: Single Event Latch-up
- SEU: Single Event Upset
- TMR: Triple Modular Redundancy